

Fault Codes Report

GS-911 version: 1303.3 Datapack version:1.2 Serial Number: GS40027501 Registered to: Stephen Parry
Date: 26/12/2013 Time: 19:47:08

BMS-K

Motorcycle VIN: WB10587017ZN72879

10444: Fuse activated for component Ignition Supply (starter relay, Immo (EWS) ring antenna, ignition coils, injectors)

The fault is not present now.

This fault occurred 4 times.

Logistic counter: 27

Symptom: No signal or value.

MIL set: No

Fault code history:

Odometer	0.0 miles	0.0 miles	0.0 miles
Engine Speed	0.00 rpm	0.00 rpm	0.00 rpm
Battery Voltage	3.30 V	2.83 V	12.25 V
Ignition Voltage	0.19 V	0.19 V	12.25 V
Time since Engine start	0.00 s	0.00 s	0.00 s

10122: Emergency Kill Switch faulty

The fault is not present now.

This problem occurred once.

Logistic counter: 38

Symptom: No signal or value.

MIL set: No

Fault code history:

Odometer	30463.5 miles
Engine Speed	600.00 rpm
Battery Voltage	11.40 V
Vehicle Speed	1.24 miles/h
Time since Engine start	163.20 s

10010: Lambda (O2) sensor (Cylinder 1)

The fault is not present now.

This problem occurred once.

Logistic counter: 28

Symptom: Signal or value over threshold.

MIL set: No

Fault code history:

Odometer	30314.4 miles
Exhaust Gas Temperature	115.00 °C
Engine Speed	1160.00 rpm

Time since Engine start	104.96 s
Lambda Sensor Voltage Bank 1	0.77 V

10219: CAN-bus Timeout: no communication with ZFE (Central Vehicle Electronics) control unit

The fault is not present now.

This fault occurred 10 times.

Logistic counter: 40

Symptom: No signal or value.

MIL set: No